

## APPENDIX H – Seismic Status, FCI, and Facility Condition Rating (Current)

**Seismic Status, FCI and Facility Condition Rating (Current)**

School Name	Facilities Condition Index (April 2021)	FCI Rate (modified based on completed SMP projects in 2021)	Seismic Risk	SMP Status
Bayview	0.38	Poor*	H1	Construction
Beaconsfield	0.39	Poor	H1	Unsupported
Begbie	0.57	Poor*	H1	Construction
Britannia Elem.	0.37	Poor	Completed	Unsupported
BRITANNIA SEC.	0.45	Poor	H1	Unsupported
Brock	0.53	Poor	H2	Unsupported
Bruce	0.69	Very Poor	H1	Unsupported
BYNG	0.48	Poor	H3	Construction
Carleton	0.56	Poor	H1	Unsupported
Carnarvon	0.71	Very Poor	H3	Unsupported
Carr	0.67	Very Poor	H1	Unsupported
Cavell	0.63	Very Poor	H1	Construction
Champlain Heights	0.52	Poor	H3	Unsupported
Champlain Heights Ax	0.75	Very Poor	M	Unsupported
CHURCHILL	0.71	Very Poor	H1	Unsupported
Collingwood Ax	0.20	Fair	Completed	Completed
Cook	0.58	Poor	Completed	Completed
Crosstown	0.00	Excellent	Completed	Completed
Cunningham	0.50	Poor	H1	Unsupported
Dickens	0.15	Fair	Completed	Completed
Dickens Ax	0.70	Poor	M	Unsupported
Douglas	0.03	Excellent	Completed	Completed
Douglas Ax	0.63	Very Poor	Completed	Completed
Elsie Roy	0.20	Fair	Completed	Completed
False Creek	0.54	Poor	H1	Supported
Fleming	0.60	Excellent*	Completed	Completed
Franklin	0.46	Poor	H1	Unsupported
Fraser	0.50	Poor	Completed	Completed
Garibaldi Ax	0.63	Very Poor	M	Unsupported
GLADSTONE	0.77	Very Poor	H1	Unsupported
Gordon	0.05	Excellent	Completed	Completed
Grandview	0.62	Poor	H1	Unsupported
Grenfell	0.51	Poor	H1	Supported
HAMBER	0.61	Very Poor*	H1	Construction
Hastings	0.54	Poor	L	Completed
Henderson	0.69	Very Poor	H3	Unsupported
Hudson	0.53	Poor*	H1	Design
Ideal Mini	0.76	Very Poor*	Completed	Completed
Jamieson	0.55	Poor	Completed	Completed
JOHN OLIVER	0.75	Very Poor	H1	Unsupported
Kerrisdale	0.67	Very Poor	Completed	Completed

School Name	Facilities Condition Index (April 2021)	FCI Rate (modified based on completed SMP projects in 2021)	Seismic Risk	SMP Status
Kerrisdale Ax	0.62	Very Poor	M	Unsupported
KILLARNEY	0.54	Poor	H1	Supported
KING GEORGE	0.68	Very Poor	H1	Unsupported
Kingsford-Smith	0.61	Very Poor	Completed	Completed
Kitchener	0.05	Good	Completed	Completed
KITSILANO	0.04	Poor	Completed	Completed
Laurier	0.68	Very Poor	Completed	Completed
L'Ecole Bilingue	<del>0.35</del>	Excellent*	Completed	Completed
Livingstone	0.44	Poor	H1	Construction
Lloyd George	0.48	Poor*	H1	Construction
Lord	0.83	Very Poor	H3	Unsupported
MacCorkindale	0.83	Very Poor	H2	Unsupported
Mackenzie	0.57	Poor	H1	Unsupported
MAGEE	0.33	Poor	Completed	Completed
Maple Grove	<del>0.47</del>	Excellent*	Completed	Completed
Maquinna	0.76	Very Poor	H3	Completed
Maquinna Ax	0.77	Very Poor	M	Unsupported
McBride	0.73	Very Poor	Completed	Completed
McBride Ax	0.52	Poor	H3	Unsupported
McKechnie	0.61	Very Poor	M	Unsupported
Moberly	0.38	Poor	Completed	Completed
Mount Pleasant	0.76	Very Poor	H3	Unsupported
Nelson	<del>0.67</del>	Excellent*	Completed	Completed
Nightingale	0.53	Poor	H1	Unsupported
Nootka	0.68	Poor	H3	Unsupported
Norma Rose Point	0.04	Excellent	Completed	Completed
Norquay	0.59	Poor	Completed	Completed
Oppenheimer	0.59	Poor	M	Unsupported
Osler	0.49	Poor	H1	Unsupported
POINT GREY	0.65	Very Poor	H1	Unsupported
PRINCE OF WALES	0.61	Poor	H1	Unsupported
QEliz Ax	0.68	Very Poor	H3	Unsupported
Queen Alexandra	0.67	Very Poor	H1	Unsupported
Queen Elizabeth	0.47	Poor	H3	Unsupported
Queen Mary	0.08	Excellent	Completed	Completed
Quesnel	0.09	Good	Completed	Completed
Quilchena	0.58	Poor	H1	Unsupported
QVic Ax	0.78	Very Poor	H3	Unsupported
Renfrew	0.48	Poor	H1	Unsupported
Roberts	0.45	Poor	M	Completed
Roberts Ax	0.62	Very Poor	M	Unsupported
Secord	0.28	Fair	Completed	Completed
Selkirk	0.48	Poor	H3	Completed
Selkirk Ax	0.68	Very Poor	H3	Unsupported

School Name	Facilities Condition Index (April 2021)	FCI Rate (modified based on completed SMP projects in 2021)	Seismic Risk	SMP Status
Sexsmith	0.03	Excellent	Completed	Completed
Seymour	0.59	Poor	H1	Unsupported
Shannon Park Ax	0.81	Very Poor	M	Unsupported
Shaughnessy	0.42	Poor	L	Completed
South Hill TA	0.61	Very Poor	H3	Completed
Southlands	0.49	Poor	H1	Unsupported
Strathcona	0.33	Poor	Completed	Completed
Tecumseh	0.73	Very Poor	M	Completed
Tecumseh Ax	0.46	Poor	M	Unsupported
TEMPLETON	0.56	Poor	H1	Unsupported
Tennyson	<del>0.68</del>	Excellent*	Completed	Completed
THOMPSON	0.67	Very Poor	H1	Supported
Thunderbird	0.34	Poor	H3	Unsupported
Tillicum Ax	0.76	Very Poor	H1	Unsupported
Total Ed.	0.71	Very Poor	Completed	Completed
Trafalgar	0.28	Fair	Completed	Completed
Trudeau	0.38	Poor	Completed	Completed
TUPPER	0.62	Very Poor	M	Completed
Tyee	0.54	Poor	M	Unsupported
University Hill	0.65	Very Poor	Completed	Completed
UNIVERSITY HILL SEC.	0.06	Good	Completed	Completed
Van Horne	0.64	Very Poor	L	Completed
VAN TECH	0.57	Poor	Completed	Completed
Waverley	0.66	Very Poor	H1	Unsupported
Waverley Ax	0.72	Very Poor	H3	Unsupported
Weir	0.63	Very Poor*	H1	Construction
WINDERMERE	0.77	Very Poor	H1	Unsupported
Wolfe	0.69	Very Poor	H1	Construction
Xpey	0.73	Very Poor	H1	Unsupported

Data Source: VFA 2021 (FCI), VSB and VPO (SMP status), MOE April 2016 (Seismic Risk)

\*school with an upgrade or replacemnt that will (or has recently) reduce FCI.



Dec. 30, 2021